

Oil Field Environmental Incident Summary

Incident: 20170620122556 **Date/Time of Notice:** 06/20/2017 12:25

Responsible Party: STATOIL OIL & GAS LP

Well Operator: STATOIL OIL & GAS LP

Well Name: RICHARD 8-5 #1H

Field Name: BANKS

Well File #: 21815

Date Incident: 6/19/2017

Time Incident: 10:30

Facility ID Number:

County: MCKENZIE

Twp: 152

Rng: 98

Sec: 8

Qtr:

Location Description:

Submitted By: James Robinson

Received By:

Contact Person: James Robinson
6300 BRIDGE POINT PKY, BLDG 2
SUITE 100
AUSTIN, TX 78730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Vessel Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

| | Spilled | Units | Recovered | Units | Followup | Units |
|------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| Oil | 1 | Barrels | 1 | Barrels | 1 | barrels |

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 6/21/2017

Clean Up Concluded: 6/19/2017

Risk Evaluation:

Minimal risk due to site containment.

Areal Extent:

Potential Environmental Impacts:

Minimal environmental impact due to site containment.

Action Taken or Planned:

PM crews are to verify from the top opening in the quad to make sure it is completely empty prior to removing manway bolts.

Wastes Disposal Location: Secure Disposal

Agencies Involved:

Updates

Date: 6/20/2017 ***Status:*** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary this spill remained on location. NDIC retains oversight.